

Cleaners Selection Guide

PRIMARY, SECONDARY & PLOWS



PRIMARY CLEANER SELECTION GUIDE

System Name	Photo	Max Belt Speed (FPM)	Min Pulley Diameter	Max Pulley Diameter	Max Belt Width	Tensioner
Eraser™ SHD		1200	24"	60"	120"	Safe Torque™
Eraser™ MDP		1200	24"	60"	96"	Safe Torque™
Super Eraser™		1000	24"	60"	96"	Safe Torque™
S3Max™		900	24"	48"	96"	Safe Torque™
Super Eraser HD™		1000	24"	60"	120"	Safe Torque™
Eraser HD™		750	16"	48"	96"	Safe Torque™
Eraser™		750	16"	32"	96"	Safe Torque™
Eraser™ RPQ		450	8"	24"	60"	Spring
Eraser™ PQ		450	8"	20"	60"	Spring
Micro Eraser™		500	8"	20"	72"	Pin Style
MES™		500	8"	20"	54"	Quick Torque™

520 9th Street • Gwinn, MI 49841
 906.226.9747 f: 906.226.9779
www.argonics.com



SECONDARY CLEANER SELECTION GUIDE

System Name	System Photo	Max Belt Speed (FPM)	Max Belt Width	Blade
XTC™		750	72"	Polyurethane
XTC™		1000	96"	Tungsten
Eraser DS™		600	72"	Polyurethane
Eraser DS™		900	72"	Tungsten
Super-G™		750	72"	Polyurethane
Super-G™		900	60"	Tungsten
Super-G XL™		900	96"	Tungsten
Chevron Belt Cleaner		500	72"	Polyurethane
Brush Cleaner		Varies	72"	Nylon bristles (others available)

PLOW CLEANER SELECTION GUIDE

System Name	System Photo	Max Belt Speed (FPM)	Max Belt Width	Mainframe
V-Max™ V-Plow		1000	96"	Steel
Aluminum V-Plow		750	72"	Aluminum
V-Max™ X-Plow		1000	96"	Steel
Aluminum X-Plow		750	72"	Aluminum